

## Inspection Photos

Location Name: COLUMBINE SP FED 8-32-4-103

Location ID: 05-103-08768

Inspection: 679701970



**Photo 1. Location looking southwest.**



**Photo 2. Tank without label.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: COLUMBINE SP FED 8-32-4-103

Location ID: 05-103-08768

Inspection: 679701970



**Photo 3. Tank without label.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources