

## Inspection Photos

Location Name: GENTRY 7-29-4-103

Location ID: 05-103-08579

Inspection: 679701972



**Photo 1. Location looking southeast.**



**Photo 2. Riser not capped or LOTO.**

## Inspection Photos

Location Name: GENTRY 7-29-4-103

Location ID: 05-103-08579

Inspection: 679701972



**Photo 3. Tank without label.**



**Photo 4. Tank without label.**

