

Inspection Photos

Location Name: Johnson A-66N64W /32SENW

Location #: 330219



Photo #1

Johnson A 32-06 (API # 05-123-18645) wellsite

Weeds

from prev. FIR



Photo #2

Johnson A 32-06 wellsite

Weeds have been cleared

