

Inspection Photos
Location Name: Roth-66N64W /30NENW
Location #: 332319



Colorado Oil & Gas Conservation Commission
40.4624, -104.59547, 1401.0m, 182°
2018/11/08 02:20:51 PM

Photo #1

Roth 21-30 (API # 05-123-22144) wellsite
Temporarily Abandoned – TA'd
*Unused Equipment – Methanol pump / tank
from prev. FIR*



Colorado Oil & Gas Conservation Commission
40.46243, -104.59546, 1402.0m, 185°
2018/12/05 04:15:56 PM

Photo #2

Roth 21-30 wellsite
**Unused Equipment – Methanol pump / tank
Has been removed**

