

Inspection Photo (s)
GMR 8-6-A1
API # 05-045-22770
Inspection # 689302509



Location Photo #1



Location Photo #2

Inspection Photo (s)
GMR 8-6-A1
API # 05-045-22770
Inspection # 689302509



Location Photo #3



Location Photo #4, Non legible chemical signs

Inspection Photo (s)
GMR 8-6-A1
API # 05-045-22770
Inspection # 689302509



Location Photo #5, unused equipment.



Location Photo #6, unused equipment.

Inspection Photo (s)
GMR 8-6-A1
API # 05-045-22770
Inspection # 689302509



Location Photo #7, Small holes in battery liner.



Location Photo #8, , Small holes in battery liner.

Inspection Photo (s)
GMR 8-6-A1
API # 05-045-22770
Inspection # 689302509



Location Photo #9, Small holes in battery liner.



Location Photo #10, Small holes in battery liner.