

Location Name: Tonto 42-23 wellsite Spill #: 459473 Inspection Date: 12/5/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Tonto 42-23 wellsite Spill #: 459473 Inspection Date: 12/5/2018



Wellhead source of spill. Water frozen on ground around wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Tonto 42-23 wellsite Spill #: 459473 Inspection Date: 12/5/2018



Pit where spilled produced water flowed. Water in pit is frozen.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Tonto 42-23 wellsite Spill #: 459473 Inspection Date: 12/5/2018



Freeboard marker is submerged. Pit does not have 2 feet of freeboard.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Tonto 42-23 wellsite Spill #: 459473 Inspection Date: 12/5/2018



Pit and wellhead where spill occurred.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Tonto 42-23 wellsite Spill #: 459473 Inspection Date: 12/5/2018



Pit and wellhead where spill occurred.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Tonto 42-23 wellsite Spill #: 459473 Inspection Date: 12/5/2018



Pit and wellhead where spill occurred.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Tonto 42-23 wellsite Spill #: 459473 Inspection Date: 12/5/2018



Drainage below well pad and produced water pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Tonto 42-23 wellsite Spill #: 459473 Inspection Date: 12/5/2018



Pit and wellhead where spill occurred. View from down hill from spill location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources