

Inspection Photos

Location Name: JOHNSON-66N65W /4NWNW

Location #: 327087



Photo #1

Johnson 11A-4 (05-123-14135) wellsite

Shut-In

Weeds

from prev. FIR



Photo #2

Johnson 11A-4 wellsite

Weeds have been cleared

Operator provided photo



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources