

Inspection Photos

Location Name: COLUMBINE SP FED 13-25-4-104, 11C-25-4-104

Location ID: 05-103-08545, 10748

Inspection: 679701984



Photo 1. Location looking northwest.



Photo 2. Separator stack without bird protection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: COLUMBINE SP FED 13-25-4-104, 11C-25-4-104

Location ID: 05-103-08545, 10748

Inspection: 679701984



Photo 3. Well 05-103-08545 TA



Photo 4. Well 05-103-10748 TA

