

Inspection Photos

Location Name: COLUMBINE SP FED 1C-23-4-104

Location ID: 05-103-10478

Inspection: 679701986



Photo 1. Lease road entrance washed out.



Photo 1. Location well head.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: COLUMBINE SP FED 1C-23-4-104

Location ID: 05-103-10478

Inspection: 679701986



Photo 3. Buried tank without label.



Photo 4. Unmarked deadman.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources