

## Inspection Photos

Location Name: COLUMBINE SP FEE 5C-24-4-104

Location ID: 05-103-10739

Inspection: 679701992



Photo 1. Location looking northwest.



Photo 2. Sign with incorrect API number.



## Inspection Photos

Location Name: COLUMBINE SP FEE 5C-24-4-104

Location ID: 05-103-10739

Inspection: 679701992



**Photo 3. Buried tank without label.**



**Photo 4. Unmarked deadman.**

