

## Inspection Photos

Location Name: COLUMBINE SP FED 1C-24-4-104

Location ID: 05-103-10509

Inspection: 679701994



**Photo 1. Location looking southeast.**



**Photo 2. Tank without label.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources