

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/27/2018

Submitted Date:

11/27/2018

Document Number:

688303003

FIELD INSPECTION FORM

Loc ID 322183 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10454
Name of Operator: PETROSHARE CORPORATION
Address: 9635 MAROON CIRCLE #400
City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Brown, Devin		dbrown@petrosharecorp.com	
Chesson, Bob		robert.chesson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209597	WELL	SI	07/01/2017	OW	039-06502	NORDMAN TRUST 32-20	SI

General Comment:

Spill reported at tank battery on 11/21/2018. Form 19I, #401848504 was submitted and approved.

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	lease sign at CR 21		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	update operator name on tanks, maintain contents and quantity labels that are wearing off		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	Tank	>= 5 bbls	
Comment:	Outside of tank was cleaned and free oil was removed. Stained soil remains (see attached photos). Per Form 19I, "The plan is to move in a hydro-vac truck on Friday to pull up contaminated soil, load it into a truck and take it to a landfill." In addition to the Initial Report to the Director, the Operator shall make a supplemental report on Form 19 not more than 10 calendar days after the spill/release is discovered that includes an 8 1/2 x 11 inch topographic map showing the governmental section and location of the spill or an aerial photograph showing the location of the spill; all pertinent information about the spill/release known to the Operator that has not been reported previously; and information relating to the initial mitigation,		
Corrective Action:	Clean up stained soils per Rule 906 and the approved Form 19I. Notify LGD and land owner if not already done.		Date: <u>12/28/2018</u>

In Containment: Yes

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 209597 Type: WELL API Number: 039-06502 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401856158	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4660153
688303023	Petroshare	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4660150