

Laramie Energy LLC
Api # 05-077-10252
Inspection # 675001429



Photo of tank battery sing at entrance .

Laramie Energy LLC
Api # 05-077-10252
Inspection # 675001429



Photo of location from South side of location

Laramie Energy LLC
Api # 05-077-10252
Inspection # 675001429



Tank on left, no labels. Tank on right, labels illegible