

Inspection Photos

API#077-08328

Operator: Black Hills

Inspection Number: 692400430

Inspection Date: 11/21/2018





Photo#1:

Overview of Location from entry to Southwest. Desirable vegetation establishment is not uniform across site

November 21, 2018




Photo#2:
Overview of Location to Northeast. Areas are infested with annual weeds..

November 21, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Currier API#077-08328



Photo#3:

Desirable vegetation establishment is not uniform across site and areas are infested with annual weeds

November 21, 2018



Photo#4:

Soils at entrance area appear to remain compacted



Photo#5:
Access road remains un-reclaimed.

November 21, 2018



Photo#6:
Access road remains un-reclaimed.