

Inspection Photos
Location Name: UPV 13-9 I 4
Location ID: 329922



Production facility



Wellhead

Inspection Photos
Location Name: UPV 13-9 I 4
Location ID: 329922



Trash on 12/12/17



Trash on 12/7/18

Inspection Photos
Location Name: UPV 13-9 I 4
Location ID: 329922



Tank berm on 12/12/17



Tank berm on 12/7/18