

Construction and Stormwater Inspection

November 28, 2018

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

Location ID: 456566

Inspection Document #: 682404249

Adams County, CO

NESE Section 33 T3S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Fraser 3-64
Location ID: 456566



Photo 1. Photo taken from a portion of the main access road, facing East. Photo illustrates the main access road has been stabilized with road base; ditch BMPs have been installed along each side of the main access road which has been stabilized with straw crimped mulch and seeded.



Photo 2. Photo taken from the northern perimeter of the location, facing East. Photo illustrates stormwater BMPs (filtrex wattles and ditch) have been installed and stabilized with straw crimped mulch and seeded. Ditch BMP has been installed around the entire perimeter of the location which is directed to a stabilized sediment trap.

Inspection Photos
Location Name: Fraser 3-64
Location ID: 456566



Photo 3. Photo taken of the northwest perimeter of the location, facing East. See comments under Photo 2. Photo also illustrates the entire well pad has been stabilized.



Photo 4. Photo taken from the northwest perimeter of the location, facing South. See comments under Photo 2 and 3.

Inspection Photos
Location Name: Fraser 3-64
Location ID: 456566



Photo 5. Photo taken from the southwest perimeter of the location, facing East. See comments under Photo 2.



Photo 6. Photo taken from the southeastern perimeter of the location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: Fraser 3-64
Location ID: 456566



Photo 7. Photo taken from the southeastern perimeter of the location, facing North. Photo illustrates the topsoil stockpile that has been stored along the eastern perimeter of the location. Stockpile has been stabilized with straw crimped mulch and seeded with filter wattle installed along the base of the stockpile.

Inspection Photos
Location Name: Fraser 3-64
Location ID: 456566



Photo 8. Photo taken from the eastern perimeter of the location, facing North. See comments under Photo 2 and 7.



Photo 9. Photo taken from the northeastern perimeter of the location, facing Northwest. Photo illustrates a sediment trap installed with a stabilized outlet.