

Final Reclamation Inspection

November 28, 2018

Operator: CONOCO PHILLIPS COMPANY- #19160

Location ID: 430595

Inspection Document #: 682404251

Adams County, CO

NWSE Section 36 T3S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: State of Colorado 36 /1

Location ID: 430595



Photo 1. Photo taken from Schumaker Road, facing East. Operator shall remove the Operator sign.

Inspection Photos

Location Name: State of Colorado 36 /1

Location ID: 430595



Photo 2. Photo taken south of the well location access road, facing West. It does not appear the access road was cross-rippled. COGCC Staff did not perform a decompaction test but the Operator should have cross-rippled to a depth of 18 inches.

Inspection Photos

Location Name: State of Colorado 36 /1

Location ID: 430595



Photo 3. Photo taken from the eastern well location, facing Southwest. No equipment was observed at the location. It is unclear whether or not the location was cross-ripped. It appears the location was only ripped one way. Operator may be required to perform additional reclamation activities (i.e., decompaction) if vegetation does not meet Rule 1004 standards.

Inspection Photos

Location Name: State of Colorado 36 /1

Location ID: 430595



Photo 4. Photo taken from the eastern well location, facing West. See comments under Photo 3.