

Inspection Photos

Operator: BP Production

API: 05-067-08701

Date: 11/9/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward.



Photo 3. View of the eastern and northeastern berm (background), that needs to be stabilized with perennial vegetation, facing northward.



Photo 5. View of kochia debris along the access road, up to 4 feet tall, needs to be removed.



Photo 5. View of Russian knapweeds (*Rhaponticum repens*) within the northwestern project area.