

# Inspection Photos

Operator: BP Production

API: 05-067-09098

Date: 11/9/2018



**Photo 1. View of the project area from the southeastern corner facing center.**



**Photo 2. View of the eastern project area from the southeastern corner facing northward.**



**Photo 3. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing, largely with grasses such as sand dropseed (*Sporobolus cryptandrus*), intermediate wheatgrass (*Thinopyron intermedium*), and crested wheatgrass (*Agropyron cristatum*).**



**Photo 4. View of Russian knapweeds (*Rhaponticum repens*) within the southeastern edge of the project area.**