

Inspection Photos

Operator: BP Production

API: 05-067-09638

Date: 11/9/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing within the interim reclamation areas and largely comprised of dense grasses such as intermediate wheatgrass (*Thinopyron intermedium*) and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of Canada thistles (*Cirsium arvense*) scattered within the interim reclamation area.