

Inspection Photos

API#045-09353

Operator: Caerus

Inspection Number: 692400438

Inspection Date: 11/30/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Southwest.

November 30, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA O'Connell API#077-09353



Photo#2:
Overview of Location from West of site to East.

November 30, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA O'Connell API#077-09353



Photo#3:
View along fill slope.

November 30, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA O'Connell API#077-09353



Photo#4:
Access road diverts from main ranch road & runs into Location.

November 30, 2018



Photo#5:
Road terminates at access to hayfields above site.