

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2018

Submitted Date:

12/10/2018

Document Number:

689702193**FIELD INSPECTION FORM**

Loc ID 311649	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 24 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284981	WELL	PR	02/01/2014	GW	045-12334	N.PARACHUTE WF 13D K25 596	PR
284982	WELL	PR	02/01/2011	GW	045-12331	N.PARACHUTE WF01C K25 596	PR
284983	WELL	PR	06/07/2008	GW	045-12333	N.PARACHUTE WF 14C K25 596	PR
284984	WELL	PR	03/29/2007	GW	045-12332	N.PARACHUTE WF03A K25 596	PR
284985	WELL	PR	01/27/2014	GW	045-12330	N.PARACHUTE WF 04A K25 596	PR
284986	WELL	PR	07/04/2008	GW	045-12329	N.PARACHUTE WF 14B K25 596	PR
284987	WELL	PR	03/29/2007	GW	045-12328	N.PARACHUTE WF05B K25 596	PR
284988	WELL	PR	03/20/2008	GW	045-12327	N.PARACHUTE WF01B K25 596	PR
291477	WELL	PR	07/20/2007	GW	045-14398	N. PARACHUTE WF16D K25596	PR
291478	WELL	PR	07/20/2007	GW	045-14399	N.PARACHUTE WF13B K25 596	PR
291533	WELL	PR	07/23/2007	GW	045-14431	N. PARACHUTE WF13C K25 596	PR
291534	WELL	PR	07/23/2007	GW	045-14430	N.PARACHUTE WF14A K25 596	PR
291535	WELL	PR	07/23/2007	GW	045-14429	N. PARACHUTE WF04C K25 596	PR
291536	WELL	PR	07/24/2007	GW	045-14438	N. PARACHUTE WF04BK25596	PR

291537	WELL	PR	07/10/2008	GW	045-14437	N. PARACHUTE WF05AK25596	PR
291538	WELL	PR	07/24/2007	GW	045-14436	N. PARACHUTE WF01A K25 596	PR
291539	WELL	PR	07/24/2007	GW	045-14432	N. PARACHUTE WF13A K25 596	PR
291540	WELL	PR	07/24/2007	GW	045-14433	N. PARACHUTE WF16C K25 596	PR
291541	WELL	PR	07/24/2007	GW	045-14434	N. PARACHUTE WF16BK25596	PR
291542	WELL	PR	03/04/2008	GW	045-14435	N. PARACHUTE WF16AK25596	PR

General Comment:[Routine FIU General Field Inspection](#)

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 20		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical containers		
Corrective Action:		Date:	

Type: Plunger Lift	# 20		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	284981	Type:	WELL	API Number:	045-12334	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284982	Type:	WELL	API Number:	045-12331	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284983	Type:	WELL	API Number:	045-12333	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284984	Type:	WELL	API Number:	045-12332	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284985	Type:	WELL	API Number:	045-12330	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284986	Type:	WELL	API Number:	045-12329	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284987	Type:	WELL	API Number:	045-12328	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284988	Type:	WELL	API Number:	045-12327	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID: 291477	Type: WELL	API Number: 045-14398	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291478	Type: WELL	API Number: 045-14399	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291533	Type: WELL	API Number: 045-14431	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291534	Type: WELL	API Number: 045-14430	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291535	Type: WELL	API Number: 045-14429	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291536	Type: WELL	API Number: 045-14438	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291537	Type: WELL	API Number: 045-14437	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291538	Type: WELL	API Number: 045-14436	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID:	291539	Type:	WELL	API Number:	045-14432	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	291540	Type:	WELL	API Number:	045-14433	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	291541	Type:	WELL	API Number:	045-14434	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	291542	Type:	WELL	API Number:	045-14435	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Compaction	Pass					
Ditches	Pass					
				Material Handling And Spill Prevention	Pass	
Berms	Pass					
		Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689702194	Inspection 689702193 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4670778