Inspection Photos

12/10/2018
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085 - 24040
Location ID: 394508
Inspection Doc. Number: 682504251
Morgan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

Photo 1: Photo taken from the well location, facing north. Photo shows various debris (concrete, pipe, metal, cable) appears to have been removed from the location.

Photo 2: Photo taken from the well location, facing east. Photo shows various debris (concrete, pipe, metal, cable) appears to have been removed from the location.

Photo 3: Photo taken from the southwest end of the disturbance area, facing north. Previous inspections that reclamation does not appear to be progressing and required operator to perform additional reclamation activities by 3/31/2018. Photos show no additional reclamation or remediation activities appear to have been conducted. The location/disturbance area remains predominantly bare and exposed soil, or undesirable weedy plant species.