

Inspection Photos

Location Name: CSF-67S91W 8SESW Pad

Location ID: #335054 Spill/Release ID: #459154

Inspection Date: November 29, 2018



Photo #1 – View of north end of tank battery SPCC from west.



Photo #2 - View of south end of tank battery SPCC from west.



Inspection Photos

Location Name: CSF-67S91W 8SESW Pad

Location ID: #335054 Spill/Release ID: #459154

Inspection Date: November 29, 2018



Photo #3 – View of remaining tank battery equipment and flowline risers inside north end of SPCC.



Photo #4 – Exposed flowline risers and potholes inside SPCC.



Inspection Photos

Location Name: CSF-67S91W 8SESW Pad

Location ID: #335054 Spill/Release ID: #459154

Inspection Date: November 29, 2018



Photo #5 – Temporary tanks are being used on pad until tank battery can be rebuilt after remediation is complete.

