

Inspection Photo (s)
Shideler 19-7B
API # 05-045-09452
Inspection # 689302585



Location Photo #1



Location Photo #2

Inspection Photo (s)
Shideler 19-7B
API # 05-045-09452
Inspection # 689302585



Location Photo #3



Location Photo #4, unmarked, unused 6" poly riser.

Inspection Photo (s)
Shideler 19-7B
API # 05-045-09452
Inspection # 689302585



Location Photo #5, Holes in secondary containment liner.



Location Photo #6, Holes in secondary containment liner.

Inspection Photo (s)
Shideler 19-7B
API # 05-045-09452
Inspection # 689302585



**Location Photo #7, Holes in secondary
containment liner.**