

Inspection Photos

Operator: BP America

API: 05-067-06785

Date: 11/14/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with grasses such as sand dropseed (*Sporobolus cryptandrus*), intermediate wheatgrass (*Thinopyron intermedium*), and foxtail barley (*Hordeum jubatum*).



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of Canada thistles (*Cirsium arvense*) within the southern project area.