

# Inspection Photos

Operator: BP America

API: 05-067-08414

Date: 11/14/2018



**Photo 1. View of the project area from the southeastern corner facing center.**



**Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with grasses such as crested wheatgrass (*Agropyron cristatum*), intermediate wheatgrass (*Thinopyron intermedium*), as well as weeds such as cheatgrass (*Bromus tectorum*).**



**Photo 3. View of the eastern project area from the southeastern corner facing northward.**



**Photo 4. View of what appears to be surface owner equipment stored in the western portion of the location.**