

Inspection Photos  
Location Name: Burkett A #2  
API: 05-067-09062



**Burkett A #2 location photo.**



**Stained gravel near well head.**

Inspection Photos  
Location Name: Burkett A #2  
API: 05-067-09062



**Burkett A #2 well head is tagged out for Spill/Release Point ID #459307.**



**Lube oil leak at Oil Lift equipment.**