

Inspection Photos

Operator: BP America

API: 05-067-08424

Date: 11/14/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with grasses such as smooth brome (*Bromus inermis*) and intermediate wheatgrass (*Thinopyron intermedium*).



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of kochia debris up to 4 feet tall along the eastern edge of the working area, needs removal.