

Inspection Photos

Operator: BP America

API: 05-067-09537

Date: 11/14/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Interim reclamation area extends outside of fencing. Revegetation is progressing with grasses such as intermediate wheatgrass (*Thinopyron intermedium*), blue grama (*Bouteloua gracilis*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of scattered musk thistles within the interim reclamation area (outside of fencing).