

# Inspection Photos

Operator: BP America

API: 05-067-09513

Date: 11/14/2018



**Photo 1. View of the project area from the northeastern corner facing center.**





**Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with grasses such as intermediate wheatgrass (*Thinopyron intermedium*), blue grama (*Bouteloua gracilis*), and sand dropseed (*Sporobolus cryptandrus*).**





**Photo 3. View of the eastern project area from the northeastern corner facing southward.**