

Inspection Photos

Operator: BP America

API: 05-067-08790

Date: 11/14/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with grasses such as intermediate wheatgrass (*Thinopyron intermedium*), blue grama (*Bouteloua gracilis*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the southern project area from the southwestern corner facing eastward.