


Inspection Photo (s)
Gypsum Ranch A-4
API # 05-045-14512
Inspection # 689302606



Location Photo #1



Inspection Photo (s)
Gypsum Ranch A-4
API # 05-045-14512
Inspection # 689302606



Location Photo #2, Tank information placard



Location Photo #3, Inaccurate tank label.

Inspection Photo (s)
Gypsum Ranch A-4
API # 05-045-14512
Inspection # 689302606



Location Photo #4, Spilled condensate in battery containment.



Location Photo #5, spilled condensate in battery containment.