

Inspection Photo (s)
Snyder A11
API # 05-045-14241
Inspection # 689302609



Location Photo #1



Location Photo #2, Unused equipment on location, poly line.

Inspection Photo (s)
Snyder A11
API # 05-045-14241
Inspection # 689302609



Location Photo #3, Unused equipment on location, poly line.



Location Photo #4, Unused equipment on location, poly line.

Inspection Photo (s)
Snyder A11
API # 05-045-14241
Inspection # 689302609



Location Photo #5, Debris/weeds near a fire source.



Location Photo #6, Debris/weeds near a fire source.

Inspection Photo (s)
Snyder A11
API # 05-045-14241
Inspection # 689302609



Location Photo #7, Unmarked deadman anchors.



Location Photo #8, Unmarked deadman anchors.

Inspection Photo (s)
Snyder A11
API # 05-045-14241
Inspection # 689302609



Location Photo #9, Unmarked deadman anchors.



Location Photo #10, Unmarked deadman anchors.