

Inspection Photos

Location Name: FORK UNIT 14-14-1-2

Location ID: 05-103-09224

Inspection: 679702113



Photo 1. Location looking south.



Photo 2. Uncapped riser.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources