

Inspection Photos

Location Name: RANGELY SOUTH 4-1-1S-102

Location ID: 05-103-08719

Inspection: 679702123



Photo 1. Location looking south.



Photo 2. Signage missing nearest public road "CR 5".



Inspection Photos

Location Name: RANGELY SOUTH 4-1-1S-102

Location ID: 05-103-08719

Inspection: 679702123



Photo 3. Signage missing capacity of 112 bbl.



Photo 4. Well head sign missing.

Inspection Photos

Location Name: RANGELY SOUTH 4-1-1S-102

Location ID: 05-103-08719

Inspection: 679702123



Photo 5. Containers missing label.

