

Inspection Photos  
Operator: Springdale Partners LLC  
Lease: Springdale Unit Baney State 16-9  
API #05-075-09247



1. Lease sign, Incorrect emergency contact number

2. Wellhead equipment, Weeds

**Inspection Photos**  
**Operator: Springdale Partners LLC**  
**Lease: Springdale Unit Baney State 16-9**  
**API #05-075-09247**



**3. Tank battery, weeds**



**4. Separator, weeds**