

**Inspection Photos**  
**Operator: Springdale Partners LLC**  
**Lease: Springdale Storage 5**  
**API #05-075-08176**



**1. Lease sign, Incorrect emergency contact number**

**2. Wellhead equipment, Weeds**

**Inspection Photos**  
**Operator: Springdale Partners LLC**  
**Lease: Springdale Storage 5**  
**API #05-075-08176**



**3. Treater and FWKO, weeds**

**4. Steel ring containment**