

**Inspection Photos**  
**Operator: Springdale Partners LLC**  
**Lease: Springdale Storage 4**  
**API #05-075-05871**



**1. Lease sign, Incorrect emergency contact number**

**2. Wellhead**