

Inspection Photos
Operator: Springdale Partners LLC
Lease: Springdale Storage 1
API #05-075-05869



1. Lease sign, Incorrect emergency contact number

2. Wellhead equipment, weeds



Inspection Photos
Operator: Springdale Partners LLC
Lease: Springdale Storage 1
API #05-075-05869



3. Steel ring containment, weeds

4. FWKO, cement containment