

Inspection Photos

12/12/2018

Operator: PRONGHORN OPERATING LLC - 10422

Location ID: 438713

Inspection Doc. Number: 682504273

Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the south end of the location, facing west. Photos 1-3 provide an overview of the location from west, north, to east. Photos also show that location remains predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted, or stabilization controls have been installed.

Inspection Photos
Operator: PRONGHORN OPERATING LLC - 10422
Location ID: 438713



Photo 2: See comment under photo 1.



Photo 3: See comment under photo 1.



Photo 4: Photo taken from the center of the location, facing north. Photos also show that location remains predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted, or stabilization controls have been installed.



Photo 5: Photo taken from the center of the location, facing east. See comments under photo 4.



Photo 6: Photo taken from the center of the location, facing south. See comments under photo 4.



Photo 7: Photo taken from the center of the location, facing west. See comments under photo 4.



Photo 8: Photo taken from the west end of the location, facing north. See comments under photo 4.



Photo 9: Photo taken from the location. Photo shows location remains predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted, or stabilization controls have been installed.



Photo 10: Photo taken from the west end of the location, facing east. See comments under photo 4.