

Inspection Photos
Location Name: Airco #2 Spill/Release
Spill/Release Point ID #458267



Photo from reported furthest extent of release.



View up gradient toward the cliff face that the release flowed over.

Inspection Photos
Location Name: Airco #2 Spill/Release
Spill/Release Point ID #458267



Area where produced water flowed over the canyon rim.



View looking downstream from near base of cliff.

Inspection Photos
Location Name: Airco #2 Spill/Release
Spill/Release Point ID #458267



Hand crew loading totes with impacted material from wash.



Stockpiled material to be removed with a helicopter on 12/18/18.