

# Inspection Photos

11/19/2018

Operator: RED HAWK PETROLEUM LLC - 10503

Location ID: 438327

Inspection Doc. Number: 682504182

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the north end of the location, facing east. Photos 1-4 provide an overview of the location from east, southeast, southwest, to west.



**Photo 2:** See comments under photo 1.



**Photo 3:** See comments under photo 1. Photo also shows no additional interim reclamation activities appear to have been conducted on the west end of the location; location has not been reduced in size.



**Photo 4:** See comments under photo 1. Photo also shows no additional interim reclamation activities appear to have been conducted on the west end of the location; location has not been reduced in size.



**Photo 5:** Photo taken from the northwestern end of the location, facing south. Photo shows no additional interim reclamation activities appear to have been conducted on areas not needed for production; location has not been reduced in size.



11.19.2018

**Photo 6:** Photo taken from the northwestern end of the location, facing east. Photo shows no additional interim reclamation activities appear to have been conducted on areas not needed for production; location has not been reduced in size.



**Photo 7:** Photo taken from the west end of the location. Photo shows erosion degradation that has not been mitigated.



**Photo 8:** 2017 COGIS aerial imagery. Photo shows areas on the west end of the location that do not appear to be necessary for production operations. These areas need to be reclaimed in accordance with COGCC 1003 interim reclamation requirements.