

Inspection Photos

Location Name: OWL CREEK STATE-66N64W /16NWSE

Location #: 332045



Photo #1

Owl Creek State 10-16 (05-123-21757) wellsite

Shut-In | LOTO

Stained soil appears remediated



Photo #2

Owl Creek State 10-16 Battery

Shut-Down

Unmarked riser at former ECD has been removed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: OWL CREEK STATE-66N64W /16NWSE

Location #: 332045



Photo #1

Owl Creek State 10-16 (05-123-21757) Battery

Stormwater erosion

from prev. FIR



Photo #2

Owl Creek State 10-16 Battery

Stormwater erosion appears mitigated



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources