

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2018

Submitted Date:

12/14/2018

Document Number:

692600953**FIELD INSPECTION FORM**
 Loc ID 304218 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone | Email                           | Comment |
|---------------|-------|---------------------------------|---------|
| Beard, Alyssa |       | regulatory@foundationenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 254213      | WELL | PR     | 04/16/1998  | GW         | 125-08091 | GODSEY 22-21  | PR          |

**General Comment:**Routine Inspection

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Trail through farm ground |       |  |
| Corrective Action  | L                         | Date: |  |

Overall Good: ☒

|                      |                    |       |  |
|----------------------|--------------------|-------|--|
| <b>Signs/Marker:</b> |                    |       |  |
| Type                 | WELLHEAD           |       |  |
| Comment:             | Lease sign by unit |       |  |
| Corrective Action:   |                    | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |   |       |  |
|--------------------|---|-------|--|
| <b>Fencing/:</b>   |   |       |  |
| Type               | PUMP JACK   |       |  |
| Comment:           | Metal panels around unit, wellhead, VGS and meter run |       |  |
| Corrective Action: |   | Date: |  |

|                           |  |       |                 |
|---------------------------|--|-------|-----------------|
| <b>Equipment:</b>         |  |       | corrective date |
| Type: Vertical Separator  | # 1  |       |                 |
| Comment:                  | Vertical gas separator 50% buried by meter run |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Pump Jack           | # 1  |       |                 |
| Comment:                  | Jensen unit                                    |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Ancillary equipment | # 2  |       |                 |
| Comment:                  | Electric panel and telemetry equipment         |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Gas Meter Run       | # 1  |       |                 |
| Comment:                  |  |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Prime Mover         | # 1  |       |                 |
| Comment:                  | Electric motor                                 |       |                 |
| Corrective Action:        |  | Date: |                 |



| Inspected Facilities |                              |       |      |             |           |         |    |               |    |
|----------------------|------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 254213                       | Type: | WELL | API Number: | 125-08091 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                              |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing production |       |      |             |           |         |    |               |    |
| Corrective Action:   |                              |       |      | Date:       |           |         |    |               |    |

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other            | Pass            | Other                   | Pass                  |               |                          |         |

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT