

Inspection Photos

Operator: BP Production

API: 05-067-09730

Date: 11/29/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the southeastern corner facing northward. Revegetation is largely comprised of grasses and shrubs such as intermediate wheatgrass (*Thinopyron intermedium*), crested wheatgrass (*Agropyron cristatum*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of erosional channels within the southwestern project area measuring up to approximately 18 inches wide and deep.



Photo 5. View of erosional channel at the entrance to the well pad measuring approximately 12 inches wide and deep.