

Inspection Photo (s)
Alp 25-16
API # 05-045-09180
Inspection # 6893026043



Location Photo #1



Location Photo #2

Inspection Photo (s)
Alp 25-16
API # 05-045-09180
Inspection # 6893026043



Location Photo #3, Several holes in battery containment liner.



Location Photo #4, Several holes in battery containment liner.

Inspection Photo (s)
Alp 25-16
API # 05-045-09180
Inspection # 6893026043



Location Photo #5, Several holes in battery containment liner.



Location Photo #6, Several holes in battery containment liner.

Inspection Photo (s)
Alp 25-16
API # 05-045-09180
Inspection # 6893026043



Location Photo #7, Piece of pipe in tank battery.