

Inspection Photos

Operator: BP Production

API: 05-067-09693

Date: 11/29/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is largely comprised of grasses such as intermediate wheatgrass (*Thinopyron intermedium*) and western wheatgrass (*Pascopyrum smithii*).



Photo 3. View of reclamation area in the eastern project area, revegetation is grazed but appears to be progressing.



Photo 4. View of erosional channels within the northern project area, measuring approximately 12 inches wide and deep.



Photo 5. View of erosional rilling and channeling within the northwestern project area.