

Inspection Photos
Location Name: Ludwig #2
Facility ID: 449950



Photo 1 – Land application area, tilling appears even and recent. Spoke with ranch manager, application of manure is concurrent with bentonitic application.



Photo 2 – Recently delivered bentonitic drill cuttings awaiting spreading.

Inspection Photos
Location Name: Ludwig #2
Facility ID: 449950



Photo 3 – Exit to east of access road, all vehicles turning north.



Photo 4 – Cattle guard acting a traction control device.