

Inspection Photos

API#045-09195


Operator: Caerus

Inspection Number: 692400452

Inspection Date: 12/14/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast.

December 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Divide Creek API#045-09195



Photo#2:
Overview from entry gate to Northeast.

December 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Divide Creek API#045-09195